



1849 Fortune Drive
San Jose, CA 95131

November 10, 2003

Product Change Notification (PCN)

Re: KS8997 Rev-A4 8port port Integrated Ethernet Switch

Dear Customer,

This PCN is to announce the following fixes in the KS8997 rev A4 silicon:

- i) The FLP amplitude has been increased from 1V to 2V
- ii) Link pulse amplitude issue fixed
- iii) 10Base-T EOI undershoot packet loss issue fixed
- iv) LED blinking due to speed mismatch issue fixed
- v) New EQ algorithm implemented
- vi) T4=1 option to disable FEF implemented

If you have any questions, please contact your local sales representatives or distributors.

Sincerely,

Grahame Cooney
Ethernet Group
Product Marketing Director