

Integrated Silicon Solution, Inc.

Process Change Notification

Date: March 1, 2004 Change Notification No. 3-3009

From: ISSI-Integrated Silicon Solution, Inc.

2231 Lawson Lane

Santa Clara, CA 95054-3311

Old Part Number

New Part Number

| IS61LV6432(TQFP/PQFP) | IS61LP6432A/ IS61LP6436A (TQFP) |
|-----------------------|---------------------------------|
| IS61S6432(TQFP/PQFP) | IS61LP6432A/ IS61LP6436A (TQFP) |
| IS61SF6432(TQFP/PQFP) | IS61LF6432A/ IS61LF6436A (TQFP) |
| IS61SF6436(TQFP/PQFP) | IS61LF6436A(TQFP) |

Description of Change:

Introducing a new die based on 0.25u technology. We are also discontinuing the support of PQFP package.

Characterization and re-qualification data is available NOW upon request. Please contact us at sram@issi.com for further information.

For customers who do not wish to migrate, Please contact <u>sram@issi.com</u> for a Last Time Buy before May 31, 2004.

Date of change: Effective Immediately